

APPLICATION STUDY RECYCLING



CUSTOMER


Hans Andersson Recycling has recycling stations in 20 facilities around Sweden where waste is processed into new raw material.

System: Baler
Make: Lindeman
Oil type: OKQ8 Handel 46
Oil volume: 3000 liters
Contact: Elie Diab

PROBLEM CONTAMINATED OIL

Customer took an oil sample. Analysis comment from independent lab. were: The oil is "heavily" contaminated!

Filtration is recommended!



SOLUTION EF2115MD

The customer chose to install Europafilter, to improve the purity.






THE RESULT ENHANCED PURITY OF OIL

A clear improvement in the purity of the oil has occurred.


Comment from the lab. after 4 months is:

"The contamination content in oil is very low"!

By using Europafilter the client prevents unexpected downtime and costly oil changes.



2012-05-08 5,9 mg/100 ml



2012-09-06 0,3 mg/100 ml



Europafilter I.M AB Olof Asklunds gata 1 421 30 V.F. Gothenburg, Sweden Ph. +46 (0)31 313 26 30 Fax.+46 (0)31 313 26 39 www.europafilter.com