

EUROPAFILTER ASSEMBLED ON TRANSMISSION BOX


Customer:
Drønen Havfiske AS,
Chief Engineer: Reidar Vassnes

Application:
Transmission gear drive box



Vessel: "MS Storeknut"


History:
Transmission gear drive box was assembled onboard "MS Storeknut" in 1996. Europafilter was assembled in January 2006. No oil changes since the EF assembly was carried out. The oil has 34000 hours of operation on the gear with the EF system in service. Total operation service hours of the gear drive box are 50500 h. The gearbox has operated approximately 15000h before the EF system assembly took place. It is common that machinery components are very clean when the lubricant system is treated with the EF system.



Scana Volda, 2000Kva, 1800 Kw,
Lubricant: Mobilgear XP 600 100



The pictures show unusual cleanliness levels inside the gear drive box.



Clean lubes...
...Clean machine